

Case Study 4

Issue




- Pad experienced sanding issues
- Sand control design was 'assumed' from prior pads
- Retrofit recompletions completed

proLAB Support & Testing

- Review sand control design cycle
- Conducted sand retention testing (SRT) and shape analysis to determine optimal sand control media

End Result

- Risk reduction with sand control failures
- Established sand control best practices
- Developed standard testing program 'per pad'
- Full paper SPE-223062-MS



Case Study 4

